Fig. 1




Fig. 2




Fig. 3




Fig. 4





Fig. 5






Fig. 7




Fig. 8




Fig. 9

REFERENCE POINT	a 1	a2	а3		n n
REFERENCE VALUE	a1p	a2p	аЗр		апр
MARGIN	X	ス	-×		7
MEASURED VALUE	a1P	a2P	а3Р		NO DATA
COMPARISON	MEASURED VALUE - REFERENCE VALUE <k< td=""><td> MEASURED VALUE MEASURED VALUE MEASURED VALUE REFERENCE VALUE - REFERENCE VALUE -</td><td> MEASURED VALUE - REFERENCE VALUE ≥k</td><td></td><td></td></k<>	MEASURED VALUE MEASURED VALUE MEASURED VALUE REFERENCE VALUE -	MEASURED VALUE - REFERENCE VALUE ≥k		
OPERATION	CONTINUE	CONTINUE	STOP CONTROL		